

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8A




FIG. 8B




FIG. 9




FIG. 10




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 12A

	A _{R1}	A _{G1}	A _{B1}	A _{R2}	A _{G2}
X ₁ Y ₁					
X ₂ Y ₂					

FIG. 12B

	A _{R1}	A _{G1}	A _{B1}	A _{R2}	A _{G2}
X ₁ Y ₁					
X ₂ Y ₂					

FIG. 12C

	A _{R1}	A _{G1}	A _{B1}	A _{R2}	A _{G2}
X ₁ Y ₁					
X ₂ Y ₂					

FIG. 12D

	A _{R1}	A _{G1}	A _{B1}	A _{R2}	A _{G2}
X ₁ Y ₁					
X ₂ Y ₂					

FIG. 12E

	AR1	AG1	AB1	AR2	AG2
X ₁ Y ₁					
X ₂ Y ₂					

FIG. 12F

	AR1	AG1	AB1	AR2	AG2
X ₁ Y ₁					
X ₂ Y ₂					

FIG. 13

